

THE AVE REDEVELOPMENT PLAN

EUCLID AVENUE REDEVELOPMENT PLAN

Steering Committee #3 Meeting November 16, 2021



AGENDA

01	SC 2 Review
02	Vacancy Analysis
03	Blighted Properties
04	Facade Conditions
05	Corridor-Wide Proposals
06	Revised PDAs



AGENDA

01	SC 2 Review
02	Vacancy Analysis
03	Blighted Properties
04	Facade Conditions
05	Corridor-Wide Proposals
06	Revised PDAs



SC 2 REVIEW

How do we get

from here







SC 2 REVIEW ENGAGEMENT SUMMARY

Priorities:

- Filling vacancies
- Improving overall look of the corridor
 - » Facades
 - » Roadway maintenance
 - » Streetscape enhancements


Building a destination
 » Commercial amenities
 » Mix of uses
 » Walkability
 Popular Areas for
 Redevelopment:
 • Former ABB

- Former Ponderosa
- South of Lloyd Rd



SC 2 REVIEW PRELIMINARY PDAS

- Business attraction / expansion
- Gathering spaces
- Job creation
- Streetscape improvements





SC 2 REVIEW

MARKET ANALYSIS

RETAIL	Can absorb approximately 100K sf of Full-Service Restaurants , Limited-Service Restaurants , and Food and Beverage Stores , and 58K sf of General Merchandise Stores.
OFFICE	Doctors' Offices only meeting 2.2% of demand. Unmet office space demand for Advertising & Marketing Services , Marketing Research & Research Development, Computer Systems Design & Management, Financial Services , and Environmental Consulting (typical sizes span wide range).
INDUSTRIAL	Unmet demand for Plastics Manufacturing (75K-300K sf per plant), Semi-Conductor Devices Manufacturing (300K-3MM sf per plant and 75K-100K sf for smaller parts), and a Food & Beverage Manufacturing Cluster (150K-270K sf per plant)
HOUSING	Aging housing stock. Need to accommodate employees - more workers drive into city for work than leave, missed opportunity. Housing costs outpacing income growth - modernized, mixed-income housing needed.
SMALL BUSINESS	Create new opportunities through cultivation, incubation, and support to combat vacancy.





01	SC 2 Review
02	Vacancy Analysis
03	Blighted Properties
04	Facade Conditions
05	Corridor-Wide Proposals
06	Revised PDAs



VACANCYANALYSIS **CORRIDOR MAP**

Approximately 180,000 SF of wholly vacant buildings 20 buildings total

Approximately 122,000 SF of vacant tenant space within partially occupied buildings/properties 16 spaces total

VACANCYANALYSIS **SAMPLE SPACE INVENTORY**



Name: Fifth Third Bank Use: Bank/ Savings Institution




Address: 29000 Euclid Ave Name: John's Bar & Grille Use: Bar/ Lounge SF: 1,364




Address: 28940 Euclid Ave Use: Discount Store/ Food SF: 9,542 Use: Scoial/Fraternal Hall SF: 6,622

STEERING COMMITTEE #3



SF: 5,244



VACANCY ANALYSIS

APPLIED MARKET ANALYSIS

	MATCHES	MISMATCHES
RETAIL	15 vacant retail spaces with an average square footage of ~3,200, generally matching with demand for health and personal care stores, electronic stores, hobby and bookstores.	Available square footage would satisfy 13% of retail demand.
	7 vacant restaurants with square footage between 1,200 and 6,600.	Available square footage would satisfy 13% of demand for restaurants.
OFFICE	5 former office spaces with varying capacities to house physician offices (only 2% local capture currently).	Available square footage would not satisfy all demand for specialized larger scale retail.
	Significant demand for larger scale office, there are at least 2 current vacancies of this size.	



01	SC 2 Review
02	Vacancy Analysis
03	Blighted Properties
04	Facade Conditions
05	Corridor-Wide Proposals
06	Revised PDAs



BLIGHT

OHIO REVISED CODE: CRITERIA 1

Meets one of the following conditions:

(a) A structure that is **dilapidated**, **unsanitary**, **unsafe**, **or vermin infested** and that because of its condition has been designated by an agency that is responsible for the enforcement of housing, building, or fire codes as **unfit for human habitation or use**;

(b) The property poses a **direct threat to public health or safety** in its present condition by reason of **environmentally hazardous conditions, solid waste pollution, or contamination**;

(c) Tax or special assessment delinquencies exceeding the fair value of the land that remain unpaid thirty-five days after notice to pay has been mailed.

BLIGHT

OHIO REVISED CODE: CRITERIA 2

Meets two of the following conditions:

- (a) Dilapidation and deterioration;
- (b) Age and obsolescence;
- (c) Inadequate provision for ventilation, light, air, sanitation, or open spaces;
- (d) Unsafe and unsanitary conditions;
- (e) Hazards that endanger lives or properties by fire or other causes;
- (f) Noncompliance with building, housing, or other codes;
- (g) Nonworking or disconnected utilities;
- (h) Is vacant or contains an abandoned structure;
- (i) Excessive dwelling unit density;
- (j) Is located in an area of defective or inadequate street layout;
- (k) Overcrowding of buildings on the land;
- (I) Faulty lot layout in relation to size, adequacy, accessibility, or usefulness;
- (m) Vermin infestation;
- (n) Extensive damage or destruction caused by a major disaster when the damage has not been remediated within a reasonable time;
- (o) Identified hazards to health and safety that are conducive to ill health, transmission of disease, juvenile delinquency, or crime;
- (p) Ownership or multiple ownership of a single parcel when the owner, or a majority of the owners of a parcel in the case of multiple ownership, cannot be located.

BLIGHT POSSIBLE PROPERTIES



BLIGHT POSSIBLE PROPERTIES





01	SC 2 Review
02	Vacancy Analysis
03	Blighted Properties
04	Facade Conditions
04 05	Facade Conditions Corridor-Wide Proposals



FACADE CONDITIONS CRITERIA


store's entrance.

BASIC

- Material
- Scale
- Activation
- Signage
- Entry
- Accessibility
- Condition

ADVANCED

- Proportion
- Composition
- Rhythm
- Detail
- Solid/Void



Cornice

Central architectural element that tops the façade. Do not cover with signage. 49

Awning

Use sturdy fabric or canvas awnings. Avoid vinyl waterfall awnings, which deteriorate quickly.


Street Number

Make the street number easy to read and locate over entrance to help customers find you.

Display Window

Make an excellent window display the centerpiece of your storefront. Avoid blocking display with signs.

FACADE CONDITIONS "GOOD" EXAMPLE



FACADE CONDITIONS



FACADE CONDITIONS "POOR" EXAMPLE





01	SC 2 Review
02	Vacancy Analysis
03	Blighted Properties
04	Facade Conditions
05	Corridor-Wide Proposals
06	Revised PDAs



CORRIDOR-WIDE CONCEPTS

DESIGN STRATEGIES

Menu of Options

» Possible strategies to achieve the vision for the corridor





• Multiple strategies can be applied throughout corridor

 Can be phased in as properties are retrofitted, and/ or supported with a dedicated streetscaping project

DEFINING THE EDGE

 PROVIDES VISUAL INTEREST AND INCREASED PEDESTRIAN COMFORT WITH PLANTERS, FENCING, TREELINES, PARKING STOPS, RETAINING WALLS, LANDSCAPING, OR BUILDINGS (LONG-TERM)

PHOTO SOURCE: SMART GROWTH AMERICA

PRIORITIZE PEDESTRIANS

- ENSURE PEDESTRIANS HAVE
 COMFORTABLE ACCESS TO ALL
 BUSINESSES
- IMPROVE CROSSWALK FREQUENCY
- INSTALL HIGH-VISIBILITY
 CROSSWALKS ON ALL APPROACHES
- PARMA HEIGHTS EXAMPLE- ROAD NOW RETROFITTED WITH HIGH VIZ CROSSINGS (STILL 5 LANES)



MANAGE PARKING

3

 RELOCATE SPOTS AWAY FROM THE STREET AND UTILIZE SIGNAGE EASILY SEEN BY DRIVERS

- ENCOURAGE SHARING ACROSS COMPATIBLE BUSINESSES; "PARK ONCE AND WALK"
- RETROFIT LARGE LOTS WITH GREENERY, TRAFFIC CALMING, PEDESTRIAN PROMENADE

PHOTO SOURCE: BUILD A BETTER BURB

REDUCE CURBCUTS

- ELIMINATING REDUNDANCIES AND NARROWING DRIVES ENCOURAGES PEDESTRIAN AND DRIVER SAFETY
- THERE ARE GOOD EXAMPLES ON THE CORRIDOR TODAY THAT REDUCE VISUAL GAPS;
 FORMALIZE ZONES; PROVIDE SAFETY BENEFITS FOR PEDESTRIANS AND DRIVERS



ENHANCE PUBLIC SPACE

PROVIDE RESTING AREAS

5

- BENCHES, SMALL PARKS, PARKLETS, AND PLAZAS ALL HELP
- CAN BE SIMPLE, LIKE LEE @ LOMOND IN SHAKER

PHOTO SOURCE: BEHNKE LANDSCAPE ARCHITECTURE



STEERING COMMITTEE #3

LIGHTING

- INCREASES FEELINGS
 SAFETY AND COMFORT
- PEDESTRIAN-SCALED LIGHTING PROVIDES ATMOSPHERE - STRING LIGHTS, WRAPPED TREES, FACADE AND LANDSCAPE UPLIGHTING
- INCREASES VISIBILITY OF
 ALL ROAD USERS

SCHOOL

STEERING COMMITTEE #3

RETROFITTING USE

 MIXING USES PROMOTES LONG-TERM RESILIENCY

- DENSITY ENCOURAGES
 DEVELOPMENT PRESSURE NEAR
 ARTERIALS
- RETROFIT FACADES (LINERS)

PHOTO SOURCE: BALTHAZAR ELYADAPTIVE (SCHOOL TO APARTMENTS)



05	Revised PDAs
05	Corridor-Wide Proposals
04	Facade Conditions
03	Blighted Properties
02	Vacancy Analysis
01	SC 2 Review




REVISED PDAS

DEVELOPMENT AREAS

Under Development

Proposed Priority





REVISED PDAS PDA 1 CONCEPT DEVELOPMENT

FINE GRAIN INFILL DEVELOPMENT INCREMENTAL / SMALL SCALE CONTEXT-SPECIFIC REDEVELOPMENT

STEERING COMMITTEE #3


SION

Z

EXT

LEY

LINERS



REVISED PDAS

PDA 3 CONCEPT DEVELOPMENT

PARK

TITT

LINER BUILDING - RETAIL

PARKING

EXISTING TO REMAIN - RETAIL

STEERING COMMITTEE #3

ENTRY 2